5X1 [23 June 1967 9619~8-67 Cy 2 of 2 cys	
	P. O. Box 8043 Southwest Station Washington, D. C. 20024	
5X1	Subject: Contract	
	Gentlemen:	
	Enclosed herewith are two (2) copies of the second monthly report for this project (9619), prepared in accordance with the requirements of Specification DB-1001.	
	Please note Paragraph D, Items Requiring Contractual Agreement.	
	The Statement of Funds expenditures as of 28 April 1967 cannot be correlated to the previous report in that the previous Statement of Funds reported expenditures as of 15 May 1967. That report was for information only, and was not required by the contract. The current report overlaps the initial report period and therefore a correlation cannot easily be made.	
	Three (3) copies of the report are being forwarded directly to the Technical Representative.	
	Very truly yours,	
	257	< 1
	cc: Technical Representative	

Declass Review by NGA.

THIS DOCUMENT CONTAINS INFORMATION AF-ECTING THE PATOMAL DEFENSE OF THE EMPLOY ETATES WITHIN THE MARRIED OF THE ESPICIT-ASE LAWS, TITLE 18 U.S.C. SECTIONS 793 AND 753, 173 TRANSMISSION OR THE REVELATION OF 175 CONTENTS IN ANY MANNER TO AN UN-AUTHORISED PERSON IS PROHIBITED BY LAW.

GROUP 1 Excluded from automatic downgrading and declassification

Approved For Release 2005/06/06 : CIA-RDP78B04770A002800010034-5

25X1

AUTOMATIC VIEWGRAPH GENERATOR

May 1 - May 31, 1967

A. Progress During Period

- Detailed layout of the various assemblies began during this period with most of the effort concentrated upon the camera assembly and the processor assembly.
- IBP purchased parts were received in part and basic dimensioning information was obtained for further design and modification of existing parts.
- 3. The light tables were received and basic layout created for incorporating the light table in the copy board.
- 4. Sensitometric evaluation of new solutions and materials was begun.
- Control panel requirements for operations and human factors

 considered and inputs from Industrial Design Department of

 were considered. Generally agreed that controls should be
 centrally located at the side of the Platemaster for optimum
 efficiency rather than in a remote control console.

B. Intended Progress During The Next Report Period.

- 1. Complete all design efforts.
- Release all items for procurement.
- 3. Complete preliminary modifications of basic IBP parts such as the magazine stand and frame assemblies to accept new assemblies.
- 4. Begin sub assembly of some portions of the machine (s).

25X1

25X1

25X1

C. Unresolved Technical Problems

D. Items Requiring Contractual Agreement

Items detailed in the last Monthly Report have not been resolved.

E. Verbal Agreements with Technical Monitor not Requiring Contractual Approval

None

F. Proposed Changes

None

G. Unresolved Matters

Reference Item D in Status Report Dated May 15th.

H. Statement of Funds

See attached Schedule.